



## Emergency procedures when working with portable gauges

1. Cease work immediately
2. Keep people nearby at least 2 metres away (approx. 6 feet) until the source is removed or until radiation levels are known to be safe
3. Immediately inform the Radiation Safety Officer (RSO):

: [jhaunerl@sfu.ca](mailto:jhaunerl@sfu.ca)

: 778-782-